

# Recall of SCOTT Speedster 2014 Road Bikes due to Fall Hazard

June 10<sup>th</sup>, 2014

In cooperation with national recall authorities, SCOTT recalls certain Scott Speedster 2014 road bikes. Consumers should stop using recalled products immediately unless otherwise instructed. It is illegal to resell or attempt to resell a recalled consumer product.



[Images of all affected bikes](#)

## Concerned Products:

2014 SCOTT Speedster with affected Forks		
Article Number	Bicycle Model Name	Potentially Affected Serial Number Range (Printed on Bicycle Frame)
234119	Speedster 30 (CD20)	AS30500001–AS30504930 AS30700001–AS30704651 AS30900001–AS30903278 AS31100001–AS31103744 AS40101604–AS40105463
234120	Speedster 40 (CD18)	
234121	Speedster 40 (27)	
234188	Contessa Speedster 25 (30)	
234189	Contessa Speedster 35 (27)	
235495	Speedster 35 (CD20) (ASP)	
235496	Speedster 45 (CD18) (ASP)	

Speedster models that are not listed above or that are not within the above mentioned serial numbers are not affected by this recall.

**Units Sold:** About 8'000 worldwide.

**Hazard:** The steerer tube in the front fork can break, creating a possible fall hazard.

**Incidents:** SCOTT has received 1 report of a fork breaking. No injuries have been reported.

**Sold at:** Authorized SCOTT dealers worldwide from about August 2013 and to May 2014.

**Made in:** Cambodia

**Remedy:** Consumers in possession of a recalled SCOTT Speedster should immediately stop using the bicycle and return it to an authorized SCOTT dealer for a free replacement of the fork.

**FAQ:**



**Consumer Contact:** For additional information, please contact SCOTT at [recall\(at\)scott-sports.com](mailto:recall(at)scott-sports.com) or call +1 888-607-8365 ext 2012 (USA) or +41 264 60 19 00 (Others).